

Blanchard Valley Health System

Laboratory Point of Care Testing

Batteries

Nova StatStrip Xpress 2 Glucose Meters

5/29/2024

| Manufactured | Technicore | Serial Numbers | Site | Location                       | In use    | R date |               | Problems | Troubleshooting |
|--------------|------------|----------------|------|--------------------------------|-----------|--------|---------------|----------|-----------------|
| 5/25/2018    | 40706      | 204066918145   | EW   | EWOC Lab                       | 11/1/2018 | Jul-18 | Energizer Max |          |                 |
| 5/25/2018    | 40705      | 204068218145   | BVMP | B V Diabetes Center            | 11/1/2018 | Jul-18 |               |          |                 |
| 5/25/2018    | 40712      | 204068818145   | BVMP | Bluffton Primary Care          | 11/1/2018 | Jul-18 |               |          |                 |
| 5/25/2018    | 40711      | 204068918145   | BVHS | Wound Care Solutions           | 11/1/2018 | Jul-18 |               |          |                 |
| 5/25/2018    | 40701      | 204069018145   | BVH  | Outpatient Lab                 | 11/1/2018 | Jul-18 | Energizer Max |          |                 |
| 5/25/2018    | 40715      | 204069218145   | BFT  | Bluffton Laboratory Outpatient | 11/1/2018 | Jul-18 |               |          |                 |

|           |       |              |     |                                 |           |        |               |   |                        |
|-----------|-------|--------------|-----|---------------------------------|-----------|--------|---------------|---|------------------------|
| 5/25/2018 | 40702 | 204069718145 | BVH | Outpatient Lab                  | 11/1/2018 | Jul-18 | Energizer Max |   |                        |
| 5/25/2018 | 40700 | 204076418145 | BVH | Bridge Inpatient Hospice        | 11/1/2018 | Jul-18 |               |   |                        |
| 5/25/2018 | 40695 | 204076618145 | BVH | BVH Lab POCT Coordinator office | 11/1/2018 | Jul-18 |               | Problem resolved after returning to Lab from Cardiac Rehab. | Extra for Lab 6/23/21. |

|           |       |              |         |                                   |            |           |               |  |                        |
|-----------|-------|--------------|---------|-----------------------------------|------------|-----------|---------------|--|------------------------|
| 5/25/2018 | 40716 | 204068518145 | BFT-01t | Ottawa Diagnostic Center          | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40707 | 204068718145 | BVMP    | Putnam County Primary Care Ottawa | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40709 | 204067818145 | BVMP    | Putnam County Primary Care Ottawa | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40698 | 204076918145 | BVMP    | Putnam Primary Care Leipsic       | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40696 | 204068318145 | BVMP    | Carey Medical Center              | 11/1/2018  | Jul-18    | Energizer Max |  |                        |
| 5/25/2018 | 40699 | 204068018145 | BVMP    | North Baltimore Med & Diag Center | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40717 | 204076718145 | BVHS    | BVH LAB Storeroom                 | 11/1/2018  | Jul-18    | Energizer Max | Returned from Plus 6/29/23. Cleaned eject button. QC ok. Back in service.              | Extra for Lab 6/29/23  |
| 5/25/2018 | 40718 | 204069318145 | BVHS    | Physicians Plus                   | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40697 | 204069618145 | BVMP    | McComb Family Practice            | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40722 | 204068618145 | BVMP    | Caughman Health Center            | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40723 | 204076818145 | BVMP    | Caughman Health Center            | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40724 | 204068418145 | BVMP    | Caughman Health Center            | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40714 | 204077018145 | BVMP    | Women and Children's Center       | 11/1/2018  | Jul-18    |               |  |                        |
| 5/25/2018 | 40694 | 204070118145 | BVMP    | Carey Diagnostic Center           | 1/20/2020  | Jul-18    |               | MISSING 5/25/22  |                        |
| 5/25/2018 | 40687 | 204071418145 | BG      | BG Bridge HH & Hospice            | 8/1/2019   | Jul-18    |               |  |                        |
| 5/25/2018 | 40688 | 204070618145 | BG      | BG Bridge HH & Hospice            | 8/1/2019   | Jul-18    |               |  |                        |
| 5/25/2018 | 40689 | 204072818145 | BG      | BG Bridge HH & Hospice            | 8/1/2019   | Jul-18    |               |  |                        |
| 5/25/2018 | 40690 | 204073318145 | BVMP    | Fostoria Primary Care             | 1/30/2020  | Jul-18    |               |  |                        |
| 5/25/2018 | 40691 | 204071118145 | BVMP    | Bluffton Pediatrics               | 4/13/2021  | Jul-18    |               |  |                        |
| 4/12/2021 | 41843 | 204037621102 | BVMP    | PANO Bluffton Pediatrics          | 10/12/2021 | 5/20/2021 |               |  |                        |
| 5/25/2018 | 40693 | 204073218145 | BVMP    | (BV Women's Care ) Lab Storeroom  | 4/7/2021   | Jul-18    | Energizer Max | E1 System Hardware Error. Returned to Lab 11/9/21, QC ok but test strip release broken | Extra for Lab 11/9/21. |
| 5/25/2018 | 40692 | 204069818145 | BVH     | BV Cardiac Rehab                  | 11/23/2020 | Jul-18    | Energizer Max |  |                        |
| 5/25/2018 | 40703 | 204067918145 | BVMP    | B V OB & GYN Bluffton             | 3/20/2020  | Jul-18    |               |  |                        |
| 5/25/2018 | 40708 | 204069118145 | BVMP    | BV Urology                        | 4/27/2021  | Jul-18    |               |  |                        |
| 5/25/2018 | 40713 | 204075918145 | BVMP    | BV OBGYN                          | 5/26/2021  | Jul-18    |               |  |                        |

|           |       |              |      |                             |            |             |               |  |  |
|-----------|-------|--------------|------|-----------------------------|------------|-------------|---------------|--|--|
| 4/12/2021 | 41841 | 204041221102 | BVH  | Wound Care Solutions        | 8/19/2021  | 5/20/2021   |               |  |  |
| 4/12/2021 | 41842 | 204039721102 | BVH  | BV OBGYN                    | 11/1/2021  | 5/20/2021   | Energizer Max |  |  |
| 8/9/2021  | 41938 | 204022421221 | BVH  | Bridgestone, Upper Sandusky | 2/1/2022   | 10/19/2021  | Energizer Max |  |  |
| 8/9/2021  | 41939 | 204023221221 | BVH  | BV OB GYN South Main        | 4/21/2022  | 10/19/2021  | Energizer Max |  |  |
| 8/9/2021  | 41940 | 204029221221 | BVMP | Gastroenterology Associates | 11/28/2022 | 10/19/2021  | Energizer Max |  |  |
| 8/9/2021  | 41941 | 204030021221 | BVH  | EWFP                        | 5/15/2023  | 10/19/2021  | Energizer Max |  |  |
| 8/9/2021  | 41942 | 204025221221 | BVH  | Carey Diagnostic Center     | 5/24/2022  | 10/19/2021  | Energizer Max |  |  |
| 8/30/2022 | 49110 | 204011822242 | BVHS | Findlay Surgery Center      | Feb-23     | R Sept 2022 | Energizer Max |  |  |
| 8/30/2022 | 49115 | 204011422242 | BVHS | Findlay Surgery Center      | Feb-23     | R Sept 2022 | Energizer Max |  |  |
| 8/30/2022 | 49118 | 204010622242 | BVHS | Findlay Surgery Center      | Feb-23     | R Sept 2022 | Energizer Max |  |  |
| 9/26/2022 | 49114 | 204051122269 | BVHS | Findlay Surgery Center      | Feb-23     | R Oct 2022  | Energizer Max |  |  |
| 9/26/2022 | 49113 | 204052322269 | BVHS | Findlay Surgery Center      | Feb-23     | R Oct 2022  | Energizer Max |  |  |

|            |       |              |      |   |           |             |               |  |  |
|------------|-------|--------------|------|---|-----------|-------------|---------------|--|--|
| 9/26/2022  | 49117 | 204050322269 | BVHS | Findlay Surgery Center                                    | Feb-23    | R Oct 2022  | Energizer Max |  |  |
| 9/26/2022  | 49116 | 204050922269 | BVHS | Returned from FSC 11/10/23                                | Feb-23    | R Oct 2022  | Energizer Max |  |  |
| 9/26/2022  | 49111 | 204051822269 | BVHS | Findlay Surgery Center                                    | Feb-23    | R Oct 2022  | Energizer Max |  |  |
| 9/26/2022  | 49112 | 204051022269 | BVHS | Returned from FSC 11/10/23<br>Infectious Disease 11/20/23 | Feb-23    | R Oct 2022  | Energizer Max |  |  |
| 10/17/2022 | 47647 | 204065022290 | BVHS | BV Laboratory Storeroom                                   |           | R12/13/2022 | Energizer Max |  |  |
| 10/17/2022 | 47648 | 204068022290 | BVHS | Physicians Plus   | 5/31/2023 | R12/13/2022 | Energizer Max |  |  |
| 10/17/2022 | 47649 | 204068322290 | BVHS | BV Laboratory Storeroom                                   |           | R12/13/2022 | Energizer Max |  |  |

DISCARDED:

|           |       |              |      |                                 |           |        |               |   |                        |
|-----------|-------|--------------|------|---------------------------------|-----------|--------|---------------|---|------------------------|
| 5/25/2018 | 40704 | 204068118145 | BVMP | Travel and Infectious Disease   | 4/1/2021  | Jul-18 | Energizer Max | E3 Error. Returned to Lab 11/21/23. E5 Error. TO BIO-MED DISCARD        | Discarded by Bio-Med.  |
| 5/25/2018 | 40710 | 204069418145 | BVHS | Wound Care Solutions            | 11/1/2018 | Jul-18 | NA            | E3 error. 2 year warranty expired 2020. 8/19/2021                       | Discarded 8/19/21. TJW |
| 5/25/2018 | 40719 | 204076218145 | BVMP | EasternWoods Family Practice    | 11/1/2018 | Jul-18 |               | Strip won't turn on - blue control dried up in port. Discarded 5/16/23. | Discarded by Bio-Med.  |
| 5/25/2018 | 40720 | 204074818145 | BVMP | Gastroenterology                | 11/1/2018 | Jul-18 | Energizer Max | Corrosion -Removed from service 11/30/2022.                             | Discarded by Bio-Med.  |
| 5/25/2018 | 40721 | 204076018145 | BVH  | BVH Lab POCT Coordinator office | 11/1/2018 | Jul-18 | NA            | Battery corrosion. 2 year warranty expired 2020. 6/23/21                | Discarded 6/23/21. TJW |

LTR51783